Nebraska Oil and Gas Conservation Commission Form 2

NOTIFICATION OF INTENT TO DRILL OR RE-ENTER								
APPLICATION TO DRILL RE-ENTER								
Instructions: Notice must be given t wells on patented or Federal lands, as	o the Director nd in quadrup	, and appr licate for w	oval obtained t	pefore proceeding ands. One appro	with the w	vork described herein. Subr Il be returned to the opera	nit this form in triplicate for itor.	
Operator								
Pan American Petrole	eum Corpo	oration	1					
Address		·						
P. O. Box 1031, Kimb	all, Nel	oraska						
			DESCRIPTION O	F WELL AND L	EASE			
Well Number	Name of Lease					Elevation (ground)		
15	V	Vowers Unit						
Well Location	A	AOMETO OTITE						
150' north				_		County		
50' west & NE SE	Sec.	33	Twp. 171	Range	54W	Banner		
rootage Location								
2138 ft. from KK (S		5	ft. from	(E) ( <b>※</b> ) line of	NE	S SE	1/4	
Field & Reservoir (If wildcat, so state	)	Will ho	le be directiona	lly drilled?		Contractor		
Vowers		N	io			Sterling Dri 11	ling C .	
Nearest distance from proposed location	on to property	or lease li	ne:	Distance from	m proposed same lease:	location to negrest drilling	g, completed or applied-for	
735			feet					
Proposed depth and deepest formation to be tested Rotary or cable tools						Approximate date work w	rill start	
6100 Muddy "J"	uddy "J" Rotary				3-15-62			
Number of acres in lease:					well, complet		eservoir:	
15								
Surface casing program:			<b>—</b>					
Amt 200 ft 5:	8-5/8			24		200		
Amt.: 200 ft. Size: Status of bond (check one)	0.370	in. O	. D.   Wt.		lbs/ft.	Cement	sacks reg	
\$2500.00 "one well" bond attached			•	\$10,000.00 Ы	anket bond o	on file X		
	- 9					0		
Permit Number:	, 😯	•		34	Will.	// m/ _		
_	***************************************	•••••••••••••••••••••••••••••••••••••••	•••••••••••••••••••••••••••••••••••••••	2	A	Signature of operator or	agent	
Approval Date: March 15, 1962				Ares	Area Superintendent			
Approval Date;	k			·	. ourell	Title &	CIVEN	
Mille	11/11	ll . 1					of CITIVED	
Approved By:	MULE	mil		3-13	-62	Dat E	KLU-51962	
		<del></del>		Ц			MARIE DIL & GOOD	
Sample cut required by Nebraska Geological Survey				Notice: Complete the location plat on reversities.				
Yes No No				be avoided.		N. C.	correct sidence will thus	
<del></del>								